

Duffy's AIS
3138 Oneida St.
Sauquoit, NY 13456

Duffy's AIS

Invoice

Phone (800) 836-1014
www.duffyais.com

Date 7/14/2020

Invoice # -062207

06/30/2020

Bill To**Service Site**

CMI MANAGEMENT
JOE BAYNE
5285 SHAWNEE ROAD
ALEXANDRIA, VA

CSS #25217
910 RAZ AVE. BLDG 1
NEW WINDSOR, NY 12553

Equipment Type

COOLER

Manufacturer	CONTINENTAL	P.O.#	JOE BAYNE	Terms	COD
Qty	Description		Price	Amount	
1	THERMOSTAT CONT		94.50	94.50T	
1	LABOR - REFRIGERATION, 1 HOUR (DIAGNOSIS)		119.00	119.00T	
1	LABOR - REFRIGERATION, 1 HOUR (REPAIR)		119.00	119.00T	
1	TRAVEL / TRIP CHARGE STANDARD		109.00	109.00T	
1	Parts Handling, freight, and carriage charge		37.95	37.95T	
1	PPE / COVID-19 COMPLIANCE FEE		7.80	7.80T	
SERVICE REQUEST: 6/9 CIB EMAIL FROM JOE BAYNE					
CALLBACK 061923					
IF NOT CALLBACK AFTER DIAGNOSIS, STOP AND CALL OFFICE FOR PREAUTHORIZATION.					

SERVICE PERFORMED: JWM 6/15/20 Check out 2 door cooler found holding at 44degrees. Condensing unit not running. Turned up temp control found compressor started. Watched box pull temp. Found					

Duffy's AIS of Schenectady now performs refrigeration service and repair on walk in coolers/freezers, ice machines, prep tables, refrigerators, freezers and more!

Service Performed by:
Duffy's AIS - Schenectady, NY

Sales Tax (8.125..

Total

PLEASE FEEL FREE TO E-MAIL SERVICE CALLS TO: SERVICE@DUFFY AIS.COM



Page 1

Payments/Credits

Balance Due

Duffy's AIS
3138 Oneida St.
Sauquoit, NY 13456

Phone (800) 836-1014
www.duffyais.com

Duffy's AIS

Invoice

Date 7/14/2020

Invoice # -062207

06/30/2020

Bill To

Service Site

CMI MANAGEMENT
JOE BAYNE
5285 SHAWNEE ROAD
ALEXANDRIA, VA

CSS #25217
910 RAZ AVE. BLDG 1
NEW WINDSOR, NY 12553

Equipment Type

COOLER

Manufacturer	CONTINENTAL	P.O.#	JOE BAYNE	Terms	COD
Qty	Description			Price	Amount
	cycling at 36degrees but doesn't come back on until 45degrees. Found thermostat no good. Provided estimate to customer, estimate was approved.				
	JWM 6/25/20 Returned to job, unplugged cooler and removed evap panel. Removed bulb from evap coil. Disconnected electrical to thermostat. Installed new thermostat and mounted bulb in evap coil. Mounted new control secured all panels and plugged in. Watched box pull temp and monitored. Found control cycled off at 36degrees and cycles back on at 41 degrees. Watched again and found same temps. Found no further issues.				
	Manufacturer: Continental Model: 2R Serial: 154C4815				

Duffy's AIS of Schenectady now performs refrigeration service and repair on walk in coolers/freezers, ice machines, prep tables, refrigerators, freezers and more!

Service Performed by:
Duffy's AIS - Schenectady, NY

Sales Tax (8.125.. \$39.59

Total \$526.84



PLEASE FEEL FREE TO E-MAIL SERVICE CALLS TO: SERVICE@DUFFY AIS.COM

Payments/Credits	-\$526.84
Balance Due	\$0.00