

Additional Funding Request

Submitted: 1/22/2019

MD021 – ceiling tiles	CSS #16730 WO#7260
Description of Repairs	Repairs to: stained, gouged, broken, missing ceiling tiles facility wide 2'x2' 64 tiles
Original SC Investigative Diagnosis	Waived
Diagnosis: Initial Work Order	S&S will remove and replace existing damaged ceiling tiles throughout the entire building up to 80 tiles (5 cases).
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	Materials: = \$249.90 (5) Radar 2ft x 2ft Lay-in ceiling tiles (64sq/ft case) @ \$47.60 ea = \$238.00 Material Tax = \$11.90
Additional Labor Cost to Perform Repairs	Labor: \$1,500.00 General Maintenance Labor Rate /20 hours/ Rate \$75.00 per hour = \$1,500.00
Total Cost of Repair	\$1,749.90