

Additional Funding Request

Submitted: 1/7/2019

MD021 – low water cut off switch	CSS #16132 WO#6426
Description of Repairs	MD 21 for boiler #3 with bad display.
Original SC Investigative Diagnosis	N/A
Diagnosis: Initial Work Order	S&S hereby diagnosed that Boiler #3 needs a new low water cut off switch
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	Materials: = \$386.70 Low water cut off # 383-600-69 = \$354.00 Tax = \$17.70 Shipping: \$15.00 **Part has 1 week lead time**
Additional Labor Cost to Perform Repairs	Labor: \$300.00 1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00
Total Cost of Repair	\$686.70