

Thursday, May 20, 2021 10:46 AM EDT

Tidewater, INC
 MD-003
 5515 Liberty Heights Ave
 Baltimore MD 21207-6999
 (410) 540-8700

Report Number: 365561-1
 Recorded By: Jon Miller
 (301) 580-9820
 jmiller@bondwater.com

5515 Liberty Heights Ave - HOT LOOP

Test	Hot Loop			
Conductivity (as mmhos)	500 3500 max			
pH	9.8 8.5 - 10			
Molybdate (ppm as Mo)	70 80 min			

Hot loop

Online 

The heating system not operating today. The readings indicate the system is holding adequate corrosion protection at this time.

Bond Water Technologies, Inc. recommends that you perform regular and/or daily analysis to control chemical levels and cycles of concentration within established limits. Test results reflect conditions during the point in time when the analysis was performed. Additional testing may be performed upon request. As operating conditions vary, test results will change over time. Notwithstanding anything to the contrary contained in the Agreement or otherwise, (i) Bond Water Technologies and its insurers are not liable for losses caused by the Customer's wrongful acts or omissions, (ii) Bond's program does not cover and it makes no guarantees with respect to waterborne pathogens including Legionella or against health risks therefrom, and (iii) in no event shall either party be liable for any consequential or indirect damages.