

Additional Funding Request

Submitted: **12/17/2021**

MD013- Flagpole Rope and Cleats	CSS #33887 WO#15955											
Description of Repairs	S&S proposes to replace the rope & cleats on the flag pole.											
Original SC Investigative Diagnosis	\$80.00											
Diagnosis: Initial Work Order	I added an FIS ticket to have the rope and cleats replace at MD013, the rope is thin and ready to break, I also requested a New US Flag for the site.											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 431.41 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Lift/Rope/Cleats</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$431.41</td> <td style="text-align: left; padding: 2px;">\$431.41</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Lift/Rope/Cleats	1	\$431.41	\$431.41
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Lift/Rope/Cleats	1	\$431.41	\$431.41									
Additional Labor Cost to Perform Repairs	Labor: \$480.00 6 hours each/Gen Maint. Rate \$80.00 per hour = \$480.00											
Total Cost of Repair	\$991.41											