

## Additional Funding Request

Submitted: 03/03/21

<b>MD013- Housing Filter</b>	<b>CSS #29040 WO# 13832</b>																
Description of Repairs	S&S herby proposes to complete the following: will shut the water off and drain down hot loop from boiler, will cut in 2 tees to hot supply and connect them while adding isolation valves and filter housing, will add supports onto new piping, will turn water back on to system and test all new piping. *This quote does not include filters.																
Original SC Investigative Diagnosis	<b>\$100.00</b>																
Diagnosis: Initial Work Order	(1 housing)- Filters that will need separate 3/4" piping and bracing run to install the housings (discharge and suction taps will need to be located or installed)--- with 3/4"shut off valves to isolate filter so service can be performed.																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p><b>Materials: \$636.21</b></p> <table border="1"> <thead> <tr> <th>ITEM</th> <th>QUANTITY</th> <th>UNIT PRICE</th> <th>TOTAL</th> </tr> </thead> <tbody> <tr> <td>[REDACTED]</td> <td></td> <td></td> <td></td> </tr> <tr> <td>Gas Pressure Safe Switch</td> <td>1</td> <td>\$453.44</td> <td>\$453.44</td> </tr> <tr> <td>Shipping</td> <td>1</td> <td>\$100.00</td> <td>\$100.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	[REDACTED]				Gas Pressure Safe Switch	1	\$453.44	\$453.44	Shipping	1	\$100.00	\$100.00
ITEM	QUANTITY	UNIT PRICE	TOTAL														
[REDACTED]																	
Gas Pressure Safe Switch	1	\$453.44	\$453.44														
Shipping	1	\$100.00	\$100.00														
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$600</b></p> <p>Plumber Labor Tech/6 hours/Rate \$100.00 per hour = \$600.00</p>																
<b>Total Cost of Repair</b>	<b>\$1,336.21</b>																