

Additional Funding Request

Submitted: 8/2/2022

MD013	CSS #1624 WO#18464
Description of Repairs	<i>S&S will remove and replace the compressor motor starter. Then, perform an operation check once completed.</i>
Diagnosis: Initial Work Order	OMS Compressor not working.
Explanation of Additional Costs for Repairs	<i>S&S will remove and replace the compressor motor starter. Then, perform an operation check once completed.</i>
Investigative Diagnosis fee from SC	\$350
Additional Material Cost to Perform Repairs	Materials \$662.89 Contactor 1.00 \$383.12 Overhead Relay 1.00 \$254.77 Shipping 1.00 \$25.00 \$25.00
Additional Labor Cost to Perform Repairs	Labor: \$600 1 HVAC Technician/6 Hours/\$100.00 rate= \$600.00
Total Cost	\$1,612.89