

Additional Funding Request

Submitted: **5/10/22**

MD066-Arms Vault Alarm	CSS #30243 WO#14148								
Description of Repairs	S&S will complete a summer change over and boiler PMs.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	Turn off heat in buildings and PM BOILER								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$ NA</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"></td><td style="text-align: left; padding: 2px;"></td><td style="text-align: left; padding: 2px;"></td><td style="text-align: left; padding: 2px;"></td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL				
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Additional Labor Cost to Perform Repairs	<p>Labor: 800.00 8 hours each/HVAC Rate \$100.00 per hour = \$800.00</p>								
Total Cost of Repair	\$800.00								