

Additional Funding Request

Submitted: 4/9/2019

MD016 – boiler damage	CSS #18544 WO #8459
Description of Repairs	Follow up of emergency service call of 2 foot of water in mechanical room.
Diagnosis: Initial Work Order	<p>S&S Mechanical is providing this quote to CMI to replace the parts for the boiler that was damaged due to motor room leak.</p> <p>❖ S&S will provide blower motor, burner control, and flame card for boiler.</p> <p>❖ S&S will provide system checks of boiler after installation of new parts.</p>
Diagnostic Fee	Diagnostic Total: NA
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00</p> <p>1 HVAC Technician /6 hours/ Rate \$100.00 per hour = \$600.00</p>
Additional Material Cost to Perform Repairs	<p>Material: \$1,818.59</p> <p>Blower Motor/VEM31111/\$515.11 Shipping: \$50.00 Burner Control/RM7895A1014/\$805.69 Shipping: \$25.00 Ultraviolet card/R7849A1023/\$227.94 Tax: \$194.85</p>
Total Cost of Repair	\$2,418.59