

**Additional Funding Request
Corrective Maintenance from PM**

Submitted: 11/13/2018

MD021 – Boiler #1, Boiler #2, temp gauges	CSS #16300 WO#6443 Asset# 2063
Description of Repairs	S&S hereby proposes to replace gauges for boiler #1 and boiler #2. S&S will provide pictures of pressures and temperature gauges once installed
Diagnosis: Initial Work Order	Replace boiler altitude gauge, does not function properly
Explanation of Additional Costs for Repairs	N/A
Investigative Diagnosis from SC	N/A
Additional Material Cost to Perform Repairs	<p>Materials: = \$96.64</p> <p>Gauge/W510218065/QTY 2 = \$ 79.92</p> <p>Tax = \$4.72</p> <p>Shipping = \$12.00</p>
Additional Labor Cost to Perform Repairs	<p>Labor:</p> <p>1 HVAC Technician/10hours/ Rate \$100.00 per hour =</p> <p>\$1,000.00</p>
Total of Corrective Maintenance Ticket	\$1,096.64
Minus \$500 – Cost of CM credit	(\$500.00)
Total Cost of Repair	\$596.64