

Additional Funding Request

MD020 Blower motor	CSS #16154 WO#6435
Description of Repairs	S&S hereby diagnosed heating call at MD20 and will need to return to install a new blower motor
Diagnosis: Initial Work Order	S&S hereby diagnosed heating call at MD20 and will need to return to install a new blower motor
Explanation of Additional Costs for Repairs	S&S hereby proposes to return to remove and install new blower motor that was found bad in room 204
Investigative Diagnosis from SC	\$350.00
Additional Material Cost to Perform Repairs	Materials: = \$329.41 Blower Motor = \$313.72 Tax = \$15.69 Shipping = \$0.00
Additional Labor Cost to Perform Repairs	Labor: = \$350.00 1 HVAC Technician /3.5hours/ Rate \$100.00 per hour = \$350.00
Estimated Repair Total	\$679.41
Full Service Total	\$1,029.41