

**Additional Funding Request
Corrective Maintenance from PM**

Submitted: 11/13/2018

| | |
|---|---|
| MD021 – Boiler #3, display board | CSS #16298 WO#6441 Asset# 2096 |
| Description of Repairs | S&S hereby proposes to return and diagnose with tech support the display board for Boiler #3: |
| Diagnosis: Initial Work Order | Certification could not be performed because of faulty control board and display module, repair and reschedule Argent |
| Explanation of Additional Costs for Repairs | N/A |
| Investigative Diagnosis from SC | N/A |
| Additional Material Cost to Perform Repairs | <u>Materials:</u> = N/A |
| Additional Labor Cost to Perform Repairs | <u>Labor:</u> 1 HVAC Technician/6hours/ Rate \$100.00 per hour = \$600.00 |
| Total of Corrective Maintenance Ticket | \$600.00 |
| CM credit | PM credit has already been applied per Rick Hicks. |
| Total Cost of Repair | \$600.00 |