

## Additional Funding Request

Submitted: 12/16/20

<b>MD0021 – Front Gate CAC Reader</b>	<b>CSS #28130 WO# 13432</b>			
Description of Repairs	LoCurrent to diagnose the issues being experienced with the CAC Reader located at the Front Gate and repair/replace the CAC Reader			
Original SC Investigative Diagnosis	N/A			
Diagnosis: Initial Work Order	REPAIR CAC READER AND POLES AT THE FRONT GATE			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$1,250.00</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	CAC Reader	1	\$1,250.00	\$1,250.00
Additional Labor Cost to Perform Repairs	<b>Labor: \$650</b> 8 hours/Rate \$75 per hour/Admin Fee \$50 =\$650.00			
<b>Total Cost of Repair</b>	<b>\$1,900.00</b>			

LoCurrent Systems, LLC  
3522 County Highway 11  
Cooperstown, NY 13326  
(607)293-7300  
locurrent@gmail.com



# Estimate

**ADDRESS**

CMI Management  
5285 Shawnee Road  
Suite 510  
Alexandria, VA 22312 USA

**ESTIMATE #** 1711  
**DATE** 12/15/2020

**P.O. NUMBER**

Rockville MD021 Front Gate Rdr

	ACTIVITY	QTY		AMOUNT
12/15/2020	<b>Services</b> CSS#28130 WO#13432 Rockville, MD021 Front Gate Diagnose, repair/replace CAC Reader  Dear Ms. Gerold:  As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the issues being experienced with the CAC Reader located at the Front Gate and repair/replace at the Rockville, MD MD021 USARC.  Cost Breakdown:  (2) men 4 hours @ \$75.....\$600.00 (1) CAC Reader.....\$1,450.00 Core Rebate.....(\$200.00) Administrative.....\$50.00  Grand Total.....\$1,900.00  The cost for the above mentioned work is not to exceed \$1,900.00.  If acceptable, please do not hesitate to contact us.	1	1,900.00	1,900.00

ACTIVITY	QTY	AMOUNT
----------	-----	--------

Thank you so much for thinking of  
LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL	\$1,900.00
-------	------------

Accepted By

Accepted Date