

Additional Funding Request

Submitted: 3/10/21

MD021- Filter Housing additional piping	CSS # 29041 WO# 13833			
Description of Repairs	S&S herby proposes to complete the following: will shut the water off at the hot water heater, will cut in two tees to the hot water line and run a 3/4" line to connect the filter housing with isolation valves on each side. S&S will turn the water back on to the system and test all new piping. *This quote does not include filter housing			
Original SC Investigative Diagnosis	\$100.00			
Diagnosis: Initial Work Order	1 housing)- Filters that will need separate 3/4" piping and bracing run to install the housings (discharge and suction taps will need to be located or installed- with 3/4shut off valves to isolate filter so service can be performed.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$494.55			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	See detail in Quote	1	\$394.55	\$394.55
	Shipping	1	\$100.00	\$100.00
Additional Labor Cost to Perform Repairs	Labor: \$600.00 Plumber Labor Tech/6 hours/Rate \$100.00 per hour = \$600.00			
Total Cost of Repair	\$1,194.55			