

## Additional Funding Request

<b>MD021 Freezer repair</b>	<b>CSS #15858 WO#6030 Asset # N/A</b>
Description of Repairs	S&S hereby proposes to install relay box needed for Kitchen refrigerator:
Diagnosis: Initial Work Order <b>CSS# 15858</b>	Freezer not working in Kitchen
Explanation of Additional Costs for Repairs	S&S hereby proposes to install relay box needed for Kitchen refrigerator:..
Investigative Diagnosis from SC	This is additional work needed
Additional Labor Cost to Perform Repairs	1 HVAC TECHNICIAN / 3 HOURS/ RATE \$100 PER HOUR = <b>\$300.00</b>
Additional Material Cost to Perform Repairs	Materials: = \$357.68 Relay Box #337-60162-02 = \$323.80 Tax = \$19.42 Shipping: \$14.46
<b>Total direct cost</b>	<b>total: \$657.68</b>