

Additional Funding Request

Submitted: 2/21/2019

MD021 – refrigerator, food prep area	CSS #17636 WO# 7585/New WO# 7910
Description of Repairs	Refrigerator not working in kitchen, food prep area
Original SC Investigative Diagnosis	\$300.00
Diagnosis: Initial Work Order	S&S went out to investigate repairs the food prep area, refrigerator not working properly. S&S will need to return to install a new compressor for the refrigerator.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	Materials: = \$585.85 Compressor/RRT62C1E-IAA-901/ qty 1 = \$534.14 Tax: \$26.71 Shipping: \$25.00
Additional Labor Cost to Perform Repairs	Labor: \$500.00 1 HVAC Technician/5hours/ Rate \$100.00 per hour = \$500.00
Total Cost of Repair	\$1,385.85