

Additional Funding Request

Submitted: 09/13/2021

MD021 – Water Softeners	CSS # 32397 WO# 15016											
Description of Repairs	S&S needs further funding to call tech support and find the issue											
Original SC Investigative Diagnosis	\$300.00											
Diagnosis: Initial Work Order	Water Softeners need to be serviced, both systems are in Alarm											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$NA <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">)</td> <td style="text-align: left; padding: 2px;"></td> <td style="text-align: left; padding: 2px;"></td> <td style="text-align: left; padding: 2px;"></td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL)			
ITEM	QUANTITY	UNIT PRICE	TOTAL									
)												
Additional Labor Cost to Perform Repairs	Labor: \$1000.00 10 hours each/Plumbing Rate \$100.00 per hour = \$1,000.00											
Total Cost of Repair	\$1300.00											