

### Over and Above Estimate

**Region:** 2

**Location:** WV024

**CSS #:** 18732

**Maximo Work Order No.:** Asset#: NA

**Date Issued:** 4/10/19

**Original Description:** Solar Inverter Repair

**Diagnosis:** Labor and material to rebuild the solar inverter.

#### Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$4,500.00		\$4,500.00
1		Shipping				\$30.00		\$30.00
1		Tax				\$362.40		\$362.40

*Note: RS Means (Pre-Priced) not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

**Estimate Summary:**

<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Material Cost</b>	<b>Equipment Cost</b>	<b>Total Cost</b>	<b>CE Factor</b>	<b>Total Estimate</b>
10 x 150= \$1,500.00	\$1,500.00	\$4,530.00		\$6,030	.90	\$5,427.00

**Please see attached estimate**

**Note:**

## Quotation

Sold-to Party Address		Information
US Army Reserve Center 1201 Hillside Ave SCHENECTADY NY 12309 USA Contact Person : Louis Corbo Phone : (518) 374-5250		Quotation No. 2410003801 Document 02/06/2019 Customer No. 1026103 Valid From 02/06/2019 Valid To 03/08/2019 Issued By JENNIFERC

Incoterms FOB Origin COL

Manufacturer

Model

Serial No.

Page 1 of 1

Quotation Details				
Item	Material Description	Quantity	Unit Price	Amount
	CASE 103503 PVI 82kW-091222-36 U.S. Army 99th Regional Support Command Ryan Linn (718) 631-6188 ryan.g.linn.civ@mail.mil  <i>Please note shipping cost and taxes will apply-Subject to change</i>  <i>Please note that core charges are now waived, core is still due to be</i> <i>returned if not returned an additional cost of \$3,500.00 will apply.</i> <i>Shipping cost and taxes will apply-Subject to change</i>			
1000	SM-LABOR PVI 82KW 091222-36	1 EA	1,500.00 per 1 EA	1,500.00
1100	R-DMGI660 REBUILT, DMGI660	1 EA	4,500.00 per 1 EA	4,500.00
1200	SM-SHIPPING FIELD SERVICE SHIPPING EXPENSES	1 EA	30.00 per 1 EA	30.00
				Tax 362.40
				Total 6,030.00