

Additional Funding Request

Site: NY023	WO# 10360 CSS # 21669 Asset# NA
Description of Repairs	Remove and replace shop sign 4x8
Diagnosis: Initial Work Order CSS# 21669	Repair 99th RD building sign outside AMSA
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 hours @\$165.00 =\$660.00
Additional Material Cost to Perform Repairs	\$975.00
Total Cost of Repair	\$1635.00

ACAV SERVICES

March 15, 2021

**REVISED ESTIMATE 100120 CSS21669
WO10360**



Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	30 DAYS
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 AMSA		
		REMOVE AND REPLACE SHOP SIGN (UPDATED FOR THE 99RD) 4X8 SIGN		
		TOTAL MATERIAL 4X8 CUSTOM ALUMINUM SIGN		\$975.00
		LABOR 4 HRS 2 \$165.00 PER HOUR		\$660.00
		TOTAL		\$1635.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581