

Additional Funding Request

Site: NY023	CSS # 22108 WO-2-6025
Description of Repairs	Replace defective faucet with Delta 8" Spread single handle
Diagnosis: Initial Work Order CSS# 20426	Repair 2nd faucet in AMSA #12 men's bathroom. Faucet will not stop running.
Explanation of Additional Costs for Repairs	Labor and Material to Replace defective faucet with Delta 8" Spread single handle
Additional Labor Cost to Perform Repairs	$2 \times \$185.00 = \370.00
Additional Material Cost to Perform Repairs	\$275.00
Total Cost of Repair	\$645.00
Notes:	