

Over and Above Estimate

Region:2

Location: NY023

CSS #: 28316

Maximo Work Order No.: 11480

Asset#:

Date Issued: 1/05/2021

Original Description: - Valves need to be replaced.

Description of Repairs: Repair Broken valves related to heating coil in ceiling mounted trane units. Drain system, trouble shoot and replace three (3) defective valves. Recharge system and check for any leaks and proper operation. Re insulate as needed

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$625.00		\$625.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
16 hours @ \$280.00	\$4480.00	\$625.00		\$5105.00	90%	\$4594.50

Please see attached estimate

ACAV SERVICES

January 8, 2021



ESTIMATE 010821 CSS28316

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 123)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG 123 AMSA REPAIR BROKEN VALVES RELATED TO HEATING COIL IN CELLING MOUNTED (TRANE) UNITS DRAIN SYSTEM TROUBLE SHOOT AND REPLACE DEFECTIVE VALVES 3EA RECHARGE SYSTEM AND CHECK FOR LEAKS AND OPERATION RE-INSULATE AS NEEDED		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u>		
		1EA 2" PRESSURE REDUCING VALVE LF225AUB-Z3		\$500.00
		2EA 1 1/2 " BALL VALVES		\$125.00
		<u>LABOR</u>		
		16 HRS @\$280.00 PER HOUR		\$4480.00
		TOTAL		\$5105.00
			TOTAL	\$5105.00