

Additional Funding Request

Site: NY023	WO# 11907 CSS # 28892
Description of Repairs	Repair Broken front entrance Security gate. Damage during snow removal, Dig out gate from snow plowed into gate, trouble shoot and replace defective runners. Realign and hand gate adjust all settings
Diagnosis: Initial Work Order	Main entrance gate stuck/froze open
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	6hrs Technician @ \$280.00 4 Hrs Laborer @ 520.00= \$2200.00
Additional Material Cost to Perform Repairs	\$200.00
Total Cost of Repair	\$2400.00

ACAV SERVICES

February 15, 2021



ESTIMATE 021521 CSS28892 WO11907

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (MAIN GATE)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 MAIN SECURITY GATE</p> <p>REPAIR BROKEN FRONT ENTRANCE SECURITY GATE</p> <p>DAMAGED DURING SNOW REMOVAL/PLOWING</p> <p>DIG OUT GATE FROM SNOW PLOWED INTO THE ACTUAL GATE</p> <p>TROUBLE SHOOT AND REPLACE DEFECTIVE RUNNERS</p> <p>REMOVE GATE INSTALL NEW LOWER RUNNER</p> <p>REALIGN AND HANG</p> <p>GATE ADJUST ALL SETTINGS</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		MATERIAL 1EA NEW LOWER RUNNER		\$200.00
		LABOR 6 HRS @ \$280.00 PER HOUR (TECHNICIAN) 4 HRS @ \$130.00 PER HOUR (LABORER)		\$1680.00 \$520.00
		TOTAL		\$2400.00
TOTAL \$2400.00				