

Additional Funding Request

Site: NY023	WO# 28209 CSS # 29209
Description of Repairs	Repair broken fence and gate. Remove gate, replace yokes and wire hangers, straighten 4" Post (4ea), straighten 2" cross members and realign and hang gate with proper adjustments
Diagnosis: Initial Work Order	Repair outside parking lot gate on the A side of Building #330
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 Hours @ 280.00 Technician= 1120.00 and 4hrs @ 130.00 Labor =520.00 Total of 1640.00
Additional Material Cost to Perform Repairs	125.00
Total Cost of Repair	\$1765.00

ACAV SERVICES

March 1, 2021



ESTIMATE 030121 CSS29209

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 330A)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG330 A REPAIR BROKEN FENCE AND GATE ON SIDE ENTRANCE REMOVE GATE REPLACE YOKES AND WIRE HANGERS STRAIGHTEN 4" POSTS 4EA STRAIGHTEN 2" CROSS MEMBERS REALIGN AND HANG GATE ADJUST ALL SETTINGS		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u>		
		2EA 2' YOKES		\$125.00
		10 WIRE HANGERS		
		<u>LABOR</u>		
		4 HRS @ \$280.00 PER HOUR (TECHNICIAN)		\$1120.00
		4 HRS @ \$130.00 PER HOUR (LABORER)		\$520.00
		TOTAL		\$1765.00
			TOTAL	\$1765.00