

Additional Funding Request

Site: NY023	WO# 12864 CSS #30383
Description of Repairs	Remove damage gate, weld broken joints and 4x4 caging screen to reinforce the gate. Rehang and align gate.
Diagnosis: Initial Work Order	Repair bottom of man entrance gate to the motor pool just outside of building #124
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	6.0 Hrs @ 250.00 per hour = \$1500.00
Additional Material Cost to Perform Repairs	\$375.00
Total Cost of Repair	\$1875.00

ACAV SERVICES

May 11, 2021



ESTIMATE 051121 CSS30383 WO 2-12864

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 124</p> <p>REMOVE DAMAGED GATE</p> <p>WELD BROKEN JOINTS</p> <p>WELD 4x7 CAGING SCREEN TO REINFORCE GATE</p> <p>REHANG GATE AND ALIGN</p> <p><u>MATERIAL</u></p> <p>4X7 CAGE MATERIAL</p> <p>BRACKETS</p> <p>WELDING SUPPLIES</p>		\$375.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>LABOR</u> 6 HRS @\$250.00 PER HOUR		\$1500.00
		TOTAL		\$1875.00
TOTAL \$1875.00				