

Additional Funding Request

Site: NY023	WO# 12866 CSS #30404
Description of Repairs	Remove and replace two Fresh 6000 CTO filters
Diagnosis: Initial Work Order	Change the Filter in the AMSA and OMS water filters, change light is on
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3.5 Hrs @ 85.00 per hour = 297.50
Additional Material Cost to Perform Repairs	\$275.00
Total Cost of Repair	\$575.50



ELKAY X
WSF6000R-2PK |
WATERSENTRY
FRESH 6000 CTO
FILTER
REPLACEMENT |
2-PACK

\$ 209.00

Subtotal \$ 209.00