

Additional Funding Request

Site: NY023	WO# 15581 CSS #33768
Description of Repairs	Drill door to fit new hardware, install customer supplied push button lock. Check operation with combination and thumb turn.
Diagnosis: Initial Work Order	Install Cipher Lock in Room 103 in Building 330A
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	\$550.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$550.00

GALAXY LOCK & ALARM, INC.

3633 E. Tremont Ave
Bronx, New York 10465



A-M8

Estimate

718-863-1365

Date
12/13/2021

Invoice #
16601

NYC LIC # 790359

Bill To:

Accounts Payable / INTL SUPPORT GROUP (GSA
VAULT)
Michele Dubois
Suite 150
9050 Pines Blvd
Pembroke Pines, FL 33024

Job Site or Ship To:

U.S Army ReserveCenter
Fort Totten
118 Duane Road
Fort Totten, NY 11359
954-900-1095x1006

PO NO:

Rep: Carl

TERMS: 14 Days

Requested By:

DESCRIPTION	QTY
B330-A OFFICE ENTRANCE DOOR= DRILL DOOR TO FIT NEW HARDWARE. INSTALL CUSTOMER SUPPLIED PUSH BUTTON LOCK. CHECK OPERATION WITH COMBINATION AND THUMB TURN.	
LABOR AS DESCRIBED	1
	Sub-Total \$550.00
	Tax \$0.00
	Total \$550.00

The above specifications and conditions are satisfactory and are accepted. You are authorized to proceed. Payment will be made as specified. Prices quoted are valid for 30 days.

SIGNATURE: _____

DATE: 12/13/2021

PRINT NAME: Michele (Shelle) Dubois