

Additional Funding Request

| | |
|---|-----------------------------------|
| Site: NY023 | WO# 15585 CSS #33782 |
| Description of Repairs | Repair Thermostat in Building 128 |
| Diagnosis: Initial Work Order | Replace defective thermostat. |
| Explanation of Additional Costs for Repairs | |
| Additional Labor Cost to Perform Repairs | 2 hours @225.00=\$450.00 |
| Additional Material Cost to Perform Repairs | \$275.00 |
| Total Cost of Repair | \$725.00 |
| | |
| | |

ACAV SERVICES

December 14, 2021



ESTIMATE 1214211 CSS33782 W015585

| Bill To | | Ship To | |
|---------------|---|-----------------|--|
| Customer | International Support Group M DUBOIS, | Recipient | 99 RSC RD DPW |
| Customer ID# | NY023 (BLDG 123) | Address | Ernie Pyle USARC BLDG 206 Ft Totten NY |
| Address | 9050 Pines Blvd STE 150 Pembroke Pines FL 33024 | Phone | 718 631 6188 |
| Phone | 954 900 1095 | | |
| Payment Due | NET 30 | Delivery Date | N/A |
| Salesperson | JW | Shipping Method | N/A |
| Payment Terms | N/A | Shipping Terms | N/A |

| Qty. | Item# | Description | Unit Price | Line Total |
|------|-------|---|------------|-----------------|
| 1 | 1 | NY023 BLDG 128 REPLACE DEFECTIVE THERMOSTAT | | |
| | | <u>MATERIAL</u> ELECTRONIC COMMERCIAL THERMOSTAT | | \$275.00 |
| | | <u>LABOR</u> 2 HRS @ \$225.00 PER HOUR | | \$450.00 |
| | | TOTAL | | \$725.00 |

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581