

Additional Funding Request

Site: NY023	WO# 16282 CSS #34182
Description of Repairs	Additional fund request to perform diagnostic.
Diagnosis: Initial Work Order	Repair 10 Ton Crane on Main Floor of AMSA #12
Explanation of Additional Costs for Repairs	Includes x2 men at 5 hours each to perform diagnostic
Additional Labor Cost to Perform Repairs	10 hours @85.00 per hour= \$850.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$850.00 for diagnostic to be performed only

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS
ISG International Support Group

ESTIMATE # 1914
DATE 01/24/2022

P.O. NUMBER
Ft Totten NY023 Diagnose Reader

	ACTIVITY	QTY	AMOUNT
01/24/2022	<p>Services</p> <p>CSS#34182 WO#16282 NY023 Ft. Totten, NY USARC Main Entrance Bldg 124 Diagnose Reader</p> <p>Dear Ms. Dubois:</p> <p>As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the issues being experienced with the Main Entrance Reader located at the Ft. Totten, NY USARC NY023 Bldg 124.</p> <p>Cost Breakdown:</p> <p>(2) men 5 hrs @ \$85.....\$850.00</p> <p>The cost to diagnose the above mentioned is \$850.00.</p> <p>If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.</p> <p>Thank you so much for thinking of LoCurrent Systems.</p> <p>Sincerely,</p> <p>Antonietta LoRusso</p>	1	850.00
			850.00

TOTAL

\$850.00

Accepted By

Accepted Date