

Additional Funding Request

Site: NY023	WO# 16630 CSS #34692
Description of Repairs	Remove, repair and seal approx. 25ft of gutter and 30ft of downspouts
Diagnosis: Initial Work Order	Repair downspout at Building 124.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 Hours @ 225.00= \$ 1800.00
Additional Material Cost to Perform Repairs	@125.00
Total Cost of Repair	\$1925.00

ACAV SERVICES

February 23, 2022



ESTIMATE 0223221 CSS34692 WO16630

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 124 (LOADING DOCK AREA)</p> <p>REPAIR LEAKING GUTTER AND DOWNSPOUT'S</p> <p>REMOVE, REPAIR AND SEAL APPX 25 FT OF GUTTERS AND 30FT OF DOWNSPOUTS</p> <p><u>MATERIAL</u></p> <p>ALUMINUM STOCK FOR PATCHING, SILICONE SEALER</p> <p><u>LABOR</u></p> <p>8 HRS @ \$225.00</p> <p>2 MEN 4 HRS EACH</p> <p>TOTAL</p>		\$125.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581