

Over and Above Estimate

Region: 2

Location: NY023

CSS # 90937

Maximo Work Order No. 90937 **Asset#:**

Date Issued: 11/28/2022

Original Description: Building 206 card reader repair the card reader is not accepting code input....however when you hit the keys it tones

Description of Repairs: Cntr will install CAC reader.

Non-Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1350.00		

Note: RS Means (Pre-Priced) is not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Equipment	Material	Total Cost	CE Factor	Total Estimate
X2 men at 8 hours each at 85.00 per hour=	\$1350.00		\$1350.0	\$2710.00	.90	\$2439.00

Please see the attached estimate.

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS
ISG International Support Group

ESTIMATE # 2143
DATE 11/28/2022

P.O. NUMBER
CSS#90937 WO#20195

ACTIVITY	QTY	AMOUNT
Services Ft. Totten, NY023 USARC Bldg. 206 CSS#90937 WO#20195 Repair/Replace CAC Reader	1	2,710.00

Dear Ms. Dubois:

As per your request, LoCurrent Systems is pleased to provide a quotation to Repair/Replace CAC Reader at Building 206 at the Ft. Totten, NY023 USARC.

Cost Breakdown:

(1) CAC Reader.....	\$1,550.00
Core Rebate.....	(\$200.00)
(2) men 8 hrs @ \$85.....	\$1,360.00
Grand Total.....	\$2,710.00

The cost for the above mentioned work is \$2,710.00.

If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed.

Thank you so much for thinking of LoCurrent Systems.

Sincerely,

ACTIVITY	QTY	AMOUNT
Antonietta LoRusso		
	TOTAL	\$2,710.00

Accepted By

Accepted Date