

Additional Funding Request

Site: NY023	WO# 21453 CSS #92248
Description of Repairs	Repair broke steam pipe in Basement. Drain the system and replace approximately 12ft x 1 ¼ in of steam pipe
Diagnosis: Initial Work Order	building 128 repair broken return heating pipe
Explanation of Additional Costs for Repairs	
Additional Labor Costs to Perform Repairs	X2 men @ 3 hours each @250.00= 1500.00
Additional Material Cost to Perform Repairs	190.00
Total Cost of Repair	\$1690.00

ACAV SERVICES

February 27, 2023



ESTIMATE 022723 CSS92248 WO21453

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 128)		
		REPAIR BROKEN STEAM PIPE IN BASEMENT		
		DRAIN STEAM SYSTEM		
		REPLACE APPROX 12FT X 1 1/4 IN STEAM PIPE		
		<u>MATERIAL</u>		
		1EA 12FT X 1 1/4 STEAM PIPE		
		2EA 1 1/4 COUPLINGS		
		1EA 1 1/4 ELBOW		\$190.00
		<u>LABOR</u>		
		6 HRS @ \$250.00		
		(2 MEN 3HRS EA)		\$1500.00
		TOTAL		\$1690.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

