

Additional Funding Request

Site: NY023	WO#21469 CSS # 93268
Description of Repairs	Repair broken lock in men's Latrine. Cut out old knop-less lock assemblies and install new knop-less lock assemblies. CNTR had to break into door, checked for any plumbing issues none found.
Diagnosis: Initial Work Order	Building 124 Repair men bathroom and replace door lock
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	900.00
Additional Material Cost to Perform Repairs	385.00
Total Cost of Repair	\$1285.00

ACAV SERVICES

March 6, 2023



ESTIMATE 030623 CSS92368 WO21469

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 124)</p> <p>REPAIR BROKEN LOCK IN MENS LATRINE</p> <p>CHECK FOR PLUMBING ISSUE</p> <p>CUT OUT OLD KNOP LESS LOCK ASSEMBLIES</p> <p>INSTALL NEW KNOP LESS LOCK ASSEMBLY</p> <p><u>MATERIAL</u></p> <p>2EA ARROW N-AUXILIARY LOCK SET \$385.00 EA</p> <p><u>LABOR</u></p> <p>4 HRS @ \$225.00 (2 MEN 2HRS)</p> <p><u>TOTAL</u></p> <p>NO PLUMBING ISSUES FOUND</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

