

Additional Funding Request

Site: NY023	WO# 21474 CSS # 92406
Description of Repairs	Repair door to the 4 th LOD storage Cage. Heat and bend frame, hand and realign door.
Diagnosis: Initial Work Order	Building 118 4th LOD cage door bent and needs to be repaired to operate and for access to unit items
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	585.00
Additional Material Cost to Perform Repairs	30.00
Total Cost of Repair	\$615.00

ACAV SERVICES

March 10, 2023



ESTIMATE 031023 CSS92406 WO21474

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 118)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 118 CAGE AREA) REPAIR DOOR TO THE 4TH LOD STORAGE CAGE HEAT AND BEND FRAME HANG AND REALIGN DOOR <u>MATERIAL</u> MISC HARDWARE NUTS AND BOLTS <u>LABOR</u> 3 HRS @ \$195.00		\$30.00
				\$585.00
		TOTAL		\$615.00
			\$	TOTAL \$615.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

