

Additional Funding Request

Site: NY023	WO# 21476 CSS # 92419
Description of Repairs	Repair broken window and window lock, Replace spring assemblies, replace lock
Diagnosis: Initial Work Order	Building 118 broken window replace and window lock
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	355.00
Additional Material Cost to Perform Repairs	675.00
Total Cost of Repair	\$1030.00

ACAV SERVICES

March 19, 2023



ESTIMATE 031923 CSS92419 WO21476

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 118)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	3 MAR 2023
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 118) REPAIR BROKEN WINDOW AND WINDOW LOCK REPLACE SPRING ASSEMBLIES REPLACE LOCK <u>MATERIAL</u> 2EA SPRING ASSEMBLIES NEW LOCK ASSEMBLY		
				\$355.00
		<u>LABOR</u> 3 HRS @ 225.00 PER HR		\$675.00
		TOTAL		\$1030.00
			TOTAL	\$1030.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

