

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 21484 CSS # 92473</b>
Description of Repairs	ISG will replace damaged and mismatched ceiling tiles
Diagnosis: Initial Work Order	Work Description : building 330 replace damaged and mismatched ceiling tiles in various offices 1st floor A side and hallways 160- 2X4 tiles.....40- 2X2 tiles
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	12 hours @ 85.00 per hour= \$1020.00
Additional Material Cost to Perform Repairs	559.50 with 20%
Total Cost of Repair	\$1579.50



## Customer Quote

3/09/2023, 6:55 PM EST

Sales Person CJB5YXP

Store Phone # (516) 488-8500

Store # 1208

Location 600 HEMPSTEAD TURNPIKE, ELMONT, NY 11003

### Customer Information

Deen Rowe

(718) 413-3472

drowehvac@gmail.com



Quote # H1208-292155

PO / Job Name

#### Delivery

Delivery Address  
330 Duane RD  
Bayside, NY 11359

Delivery Options  
Outside Delivery

Delivery Date  
Delivery to be scheduled at the time of purchase

Item Description	Model #	SKU #	Unit Price	Qty	Subtotal
Armstrong CEILINGS Brighton 2 ft. x 2 ft. Drop Ceiling Tile (64 sq. ft. / case)	266B	129613	\$62.58 / each	1	\$62.58
Armstrong CEILINGS Esprit 2 ft. x 4 ft. Lay-in Ceiling Tile (128 sq. ft. / case)	403A	237924	\$119.00 / each	3	\$357.00
Outside Delivery		515663	\$8.99 / each	1	\$8.99

**Prices Valid Through:** 03/16/2023  
at The Home Depot #1208

Subtotal	\$428.57
Discounts	-\$0.00
Sales Tax	\$38.04
<b>Quote Total</b>	<b>\$466.61</b>