

CERTIFICATION OF WORK	
(To be completed by the Contractor and saved in the Contractor's CMMS)	
FACID/Building:	<u>NY29 OWS 370 A</u>
Location Address:	<u>FT TOWNE</u>
Date of Visit: <u>11/11/23</u>	
Contractor Personnel on Site:	
<u>Timothy, Tom</u>	
Work Performed: <u>Run diag on AK Pump ran 214</u>	
Service Calls – PO/CSS#	
<u>65594827 NO 23257 PO 1004-105</u>	
Please take pictures and send with quote	
CERTIFICATION OF WORK	
To be signed by the Contractor:	
Print Name:	<u>Taylor Woldm</u>
Signed:	<u>dw</u>
Date:	<u>11/11/23</u>
To be signed by Facility Manager:	
I certify that the above named individuals representing the Contractor arrived on site.	
Print Name/Rank:	<u>Louis Corbo</u>
Signed:	<u>Louis Corbo</u>
Date:	<u>11/11/23</u>
Email:	<u>Louis.A.Corbo-civ@Army.mil</u>

