



INVOICE

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

September 13, 2020

RE: Orangeburg water on floor
NY050 Css# 000xxx

- Remove drop ceiling panels adjacent to wall.
- Cut dry wall above ceiling and inspect for water leaks or stains.
- Remove baseboard and cut drywall and inspect for leaks or stains inside wall at floor.
- No water source found from above. It was raining the morning of inspection.

Total. 450.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL