

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
KITCHEN RANGE HOOD

ACTIVITY AND BLDG #: NY058-104

MECHANIC

Deen Row

12/15/20

LOCATION: *Kitchen*

SIGNATURE:

DATE:

START TIME: *2pm*

FINISH TIME: *230pm*

| Site Location | WO # | Asset # | PM # | Manufacturer | Model Number | Serial # | Asset Description | Asset Location |
|---------------|-------|---------|-------------|---------------------------------|--------------|----------|------------------------|----------------|
| NY058-104 | 10892 | 10329 | PM-SA-10329 | Kitchen Ventilation Specialists | 1462 | | J-38 1-pc Kitchen Hood | |
| | | | | | | | | |
| | | | | | | | | |

| CHECK POINT | CHECKPOINT DESCRIPTION | TASK COMPLETE | | NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION) |
|---|---|---------------|----|---|
| | | YES | NO | |
| SPECIAL INSTRUCTIONS | | | | |
| 1 | In addition to the procedure(s) outlined in this standard, the equipment manufacturer's recommended maintenance procedure(s) and/or instruction(s) shall be strictly adhered. | ✓ | / | |
| 2 | Review manufacturer's instructions. | ✓ | / | |
| 3 | always Follow lock out/tag out procedures . De-energize or discharge all hydraulic, electrical, mechanical, or thermal energy prior to beginning work. | ✓ | / | |
| TO BE PERFORMED AT EACH INSPECTION SERVICE | | | | |
| 1 | Remove filters, scrape and wash plenum walls, filter frames and fire suppression equipment (not including the fusible links and trigger mechanisms). | ✓ | / | |

| | | | | |
|---|---|-------------------------------------|--------------------------|--|
| 2 | Scrape and/or brush the interior surfaces of all accessible horizontal and vertical ductwork. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 3 | Wash all fan blades, interior and exterior of fan housing and drip pans (hot, high pressure wash when possible). | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 4 | Clean all louvers and dampers. If dampers must be moved to ensure complete cleaning, they will be marked and returned to their original position to prevent unbalancing the system. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |
| 5 | Replace filters to their original position | <input checked="" type="checkbox"/> | <input type="checkbox"/> | |

Note: The Contractor shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence.

Checklist compiled in accordance with:

- Original equipment manufacturers (OEM) documentation for exact or similar assets, which can be located at [\(Provide Link to OEM Manual/Asset Library\)](#)

Additional Notes:

Page 1 of 1

