

Additional Funding Request

Site: NY023	WO# 11481 CSS # 28350
Description of Repairs	Remove and replace defective (2) Seimens model GMA221 1 U Actuators
Diagnosis: Initial Work Order	Replace defective actuators on Boilers 2 and 3 in the Main Boiler Room
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs @ \$225.00= \$1800.00
Additional Material Cost to Perform Repairs	\$590.00
Total Cost of Repair	\$2390.00

ACAV SERVICES

January 6, 2021



ESTIMATE 010621 CSS28350

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	<p>NY058 MAIN BLDG (BOILER ROOM)</p> <p>REPLACE DEFECTIVE (2) SIEMENS MODEL GMA221 1 U ACTUATORS ON BOILERS 2 AND 3</p> <p>MATERIAL</p> <p>2 EA SIEMENS MODEL GMA221 1 U ACTUATORS 2 EA @ \$295.00 EA</p> <p>LABOR</p> <p>8 HRS @ \$225.00 PER HOUR</p> <p>TOTAL</p>		\$590.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581