

Additional Funding Request

Site: NY058	WO# 14931 CSS #32761
Description of Repairs	Remove and replace two defective electric wall mounted heaters in the pump house. Replace two 30amp breakers
Diagnosis: Initial Work Order	Install electrical heaters in 2 pump stations.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3 hours at \$235.00= \$705.00
Additional Material Cost to Perform Repairs	\$1485.00
Total Cost of Repair	\$2190.00

ACAV SERVICES

October 6, 2021



ESTIMATE 100621 CSS32761

Bill To		Ship To	
Customer	INTERNATIONAL SUPPORT GROUP M DUBOIS	Recipient	99 RSC DPW
Customer ID#	NY058 (Shoreham USARC)	Address	Ernie Pyle USARC BLDG 200 Ft Totten NY
Address		Phone	718 631 6188
Phone	718 790 3562		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms		Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY058 Shoreham USARC (FIRE SYSTEM PUMP HOUSE) REPLACED 2EA DEFECTIVE ELECTRIC WALL MOUNTED HEATERS IN THE PUMP HOUSE REPLACED <u>2EA</u> 30AMP BREAKER MATERIAL 2EA WALL MOUNTED ELECTRIC HEATERS 2EA 30AMP BREAKERS <u>LABOR</u> 3 HRS @ 235.00 PER HOUR TOTAL NO TAX		 \$705.00 \$1485.00 \$2190.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581