

Over and Above Estimate

Region: 2

Location: NY058

CSS #:90573

Maximo Work Order No. 19761 **Asset#:**

Date Issued: 10/31/2022

Original Description: Rewire boiler #4, it is not communicating with controls

Description of Repairs: # 4 Boiler is not firing. Cntr will rewire boiler controls, replace high limit control and replace low water cut off.

Non-Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				1003.00		

Note: RS Means (Pre-Priced) is not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Equipment	Material	Total Cost	CE Factor	Total Estimate
12 hrs @ 250.00=3000.00	\$3000.00		1003.00	\$4003.00	.90	\$3602.70

Please see the attached estimate.

ACAV SERVICES

November 23, 2022



ESTIMATE 112322 CSS90573 WO19761

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW L CORBO
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qt y.	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BLDG #4 BOILER NOT FIRING REWIRE BOILER CONTROLS REPLACE HIGH LIMIT CONTROL REPLACE LOW WATER CUT OFF <u>MATERIAL</u> HIGH LIMIT CONTROL LOW WATER CUT OFF <u>LABOR</u> 12 HRS @ \$250.00 PER HOUR		\$1003.00
				\$3000.00
		TOTAL		\$4003.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

