



PROPOSAL - CONTRACT

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

March 25, 2020

RE
CSS# 24577 NY116 New Windsor
AFRC HVAC# 4 in the first floor
mechanical room
is leaking water from a supply
line.

- Isolate compromised fitting.
- Remove fitting (s) as necessary and replace.
- Remove and re-install existing pipe insulation.
- check for leaks.

1 Misc copper fittings and solder 50.00

sub total 50.00

8hrs @120.00. 960.00

sub total. 1010.00

20% profit/OH. 202.00

Total. 1212.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX 518-399-5440

Email rdpostulka@verizon.net

INDUSTRIAL

COMMERCIAL

INSTITUTIONAL