

Date: 2-6-26



Region: 4A

FEMS/CSS No.: 3497094

FAC ID: PA027

Maximo WO No.: 21214

Asset #:

Priority: 3

Original Work Request:

Repair by replacement of interior office door handle, room 148C that will no longer lock

Description of Repairs Needed:

Replace door handle on interior door and ensure properly operating

Labor:

| | Labor Hrs | Labor Rate | Total |
|----------|-----------|------------|-----------|
| Tech (1) | 1 | \$ 100.00 | \$ 100.00 |
| | | | \$ - |
| | | | \$ - |

Material List:

| | Quantity | Cost | Total |
|---------------------------------|----------|-----------|-----------|
| Storeroom Knob Lockset (429K96) | 1 | \$ 159.95 | \$ 159.95 |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |

Equipment List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |

PM WO History:

Estimate Summary:

| Labor | Material | Equipment |
|----------|----------|-----------|
| \$100.00 | \$159.95 | \$0.00 |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|-----------|---------|---------|----------------|
| \$259.95 | \$31.19 | \$15.60 | \$306.74 |