

Date: 9-20-25

Region: 4A

FEMS/CSS No.: 3313540

FAC ID: PA063

Maximo WO No.: 20306

Asset #:

Priority: 2



Original Work Request:

Trouble alarm stating something is disabled in the OMS fire panel

Description of Repairs Needed:

Proposal is to provide a team of fire alarm techs to investigate and troubleshoot outstanding fire alarm trouble at PA063. Tech will attempt to correct/address issue during initial visit; however, if a second follow up visit is required with additional repairs, a separate additional proposal will be provided

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 154.00	\$ 1,232.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,232.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,232.00	\$147.84	\$73.92	\$1,453.76