

Date: 01-28-26

Region: 4A

FEMS/CSS No.: 3313548

FAC ID: PA063

Maximo WO No.: 21196

Asset #:

Priority:  3



**Original Work Request:**

Two door refrigerator is no longer cooling, we have tried resetting but it still is not working properly.

**Description of Repairs Needed:**

Proposal is to add refrigerant and sealant to the refrigerator to recharge and stop leak.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
refrigerant 134A (8.6 oz)	1	\$ 80.00	\$ 80.00
easy seal direct inject (1GR3271D)	1	\$ 61.11	\$ 61.11
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$250.00	\$141.11	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$391.11	\$46.93	\$23.47	\$461.51