

Date: 8/7/2023

Region: 4C

FAC ID: PA118

CSS No.: 12770

Maximo WO No.: 93238

Asset #:

Priority: 3



Original Work Request:

Repair fire extinguisher Tag #34, serial #A-240899637, Model Amerex 423, Size 20#, Type ABC and Tag #35, Serial #A-24089589, Model Amerex 423, Size 20#, Type ABC

Description of Repairs Needed:

Replace 2 - 20lb ABC Extinguishers identified during fire system inspection for replacement.

Labor:	Labor Hrs	Labor Rate	Total
1 Tech	1.5	\$ 120.00	\$ 180.00
			\$ -

Material List:	Quantity	Cost	Total
20lb ABC Extinguishers	2	\$ 250.00	\$ 500.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$180.00	\$500.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$680.00	\$81.60	\$40.80	\$802.40