

Date: 11-05-24

Region: 4A
FAC ID: PA118

FEMS No.: 2935178
Maximo WO No.: 17088

Asset #:

Priority: 3



Original Work Request:

Perform load test on 10 ton overhead crane located in the high bay. Load test is required to meet OSHA standards. The load test has not been done in the last 5 yrs as we have no testing on file,

Description of Repairs Needed:

Provide service technicians on site to perform load test of (1) crane and hoist of 10 ton capacity. U.S. Crane to supply lift as necessary and as need to access crane and hoist.

Labor:

	Labor Hrs	Labor Rate	Total
Techs (1)	8	\$ 110.00	\$ 880.00
			\$ -

Material List:

	Quantity	Cost	Total
Rental Weights (to/from transportation, motorized buggy		\$	-
cart, fuel surcharges, regulatory compliance fees, testing		\$	-
standards	1	\$ 3,390.00	\$ 3,390.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 645.00	\$ 645.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$880.00	\$3,390.00	\$645.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,915.00	\$589.80	\$294.90	\$5,799.70