

Date: 4-09-25

Region: 4A

FEMS/CSS No.: 2934823

FAC ID: PA209

Maximo WO No.: 18525

Asset #:

Priority: 3



Original Work Request:

Handicap showers in both men and women locker rooms need to be repaired as they are leaking. The leads are mainly from the hardware for the handheld shower heads

Description of Repairs Needed:

Replace shower heads, diverter, cartridge in handicap showers that are currently leaking.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	5	\$ 100.00	\$ 500.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Zurn RK7000-50 Cartridge	2	\$ 60.00	\$ 120.00
Zurn RK7073-50, 2-way, 3-way rplcment stem F/Divter	2	\$ 41.00	\$ 82.00
Zurn Z7000-S5- 1.5GPM Brass Shwr Head	2	\$ 75.85	\$ 151.70
Shower Head, RP38357 PC Touch Clean Chrome Plate	2	\$ 31.35	\$ 62.70
Misc shop supplies (rags, lubricants, gasket, ...)	1	\$ 20.00	\$ 20.00
shipping	1	\$ 50.00	\$ 50.00
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$500.00	\$486.40	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$986.40	\$118.37	\$59.18	\$1,163.95