

Date: 4-17-25

Region: 4A

FEMS/CSS No.: 2935159

FAC ID: PA209

Maximo WO No.: 18778

Asset #:

Priority: 2



Original Work Request:

Repair leaking actuator for HW heating. The actuator is leaking in the mechanical room next to AS-1

Description of Repairs Needed:

Proposal to assess leaking actuator valve for repair.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) - Investigate	8	\$ 156.00	\$ 1,248.00
Trip Charge - Investigate	1	\$ 180.00	\$ 180.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,428.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,428.00	\$171.36	\$85.68	\$1,685.04