

Date: 8/28/2023

Region: 4A
FAC ID: NY052

CSS No.: 94832
Maximo WO No.: 13850

Asset #: NA

Priority: Urgent



Original Work Request:

Repair additional gas leaks. More gas leaks were detected in OMS building. This is a follow up to ticket 94394.

Description of Repairs Needed:

Labor and material to a.) run new gas pipe from gas meter to newer section of gas piping inside building. b.) Run gas piping to 2 ceiling units. c.) Pressure test will be repeated when repair is complete to ensure not leaking will occur.

Labor:

	Labor Hrs	Labor Rate	Total
2 Technicians	8	\$ 268.50	\$ 2,148.00
Trip Charge	1	\$ 450.00	\$ 450.00

Material List:

	Quantity	Cost	Total
Misc Materials	1	\$ 434.12	\$ 434.12
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Boom Lift and Gas Threader Rental	1	\$ 2,849.81	\$ 2,849.81
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 2,598.00	\$434.12	\$2,849.81

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,881.93	\$705.83	\$352.92	\$6,940.68

Hello, this is your estimate
Location: 198 Cornwell Street, Penn Yan, NY, 14527

JOB ID
4851973

Main pipe replacement


Your Price
\$5,881.93

Accept Now

Summary

Run new gas pipe from gas meter to newer section of gas piping inside building. Run gas piping to 2 ceiling units. Pressure test will be repeated when repair is complete to ensure not leaking will occur.


Gas line repair breakdown:
Labor - \$2148.00
Materials - \$434.12
Trip charge - \$450.00
Equipment Rental - \$2849.81



ST168

Your Price
\$450.00


Trip Charge



ST168

Your Price
\$2,849.81

Boom Lift and Gas Threader Rental

**ST168**

Your Price

\$2,582.12

Repair of main gas line and connecting to upper portion of line within building

Subtotal	\$5,881.93
Tax	\$0.00
Total	\$5,881.93